Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	0	@ad<"20011220" and all adj flash adj PC	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/01/02 11:29
L2	0	@ad<"20011220" and flash adj only near computer	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/01/02 11:29
L3	0	@ad<"20011220" and flash adj memory near only near computer	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/01/02 11:29
L4	3	@ad<"20011220" and flash adj memory near based near computer	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/01/02 11:32
L5	0	@ad<"20011220" and firmware adj update near peripheral adj card	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/01/02 11:33
L6	2	@ad<"20011220" and firmware adj update and peripheral adj card	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/01/02 11:34
L7	0	@ad<"20011220" and firmware adj update near peripheral and assembly adj line	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/01/02 11:34
L8	0	@ad<"20011220" and firmware adj update near peripheral and assembly	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/01/02 11:34
L9	1	@ad<"20011220" and firmware adj update near peripheral	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/01/02 11:35

L10	1	@ad<"20011220" and firmware adj update near peripheral and wireless	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/01/02 11:37
L11	0	@ad<"20011220" and firmware adj update same PCI adj card and wireless	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/01/02 11:37
L12	0	@ad<"20011220" and firmware adj update same PCI adj card	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/01/02 11:37
L13	0	@ad<"20011220" and firmware adj update same peripheral near card	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/01/02 11:37
L14	0	@ad<"20011220" and firmware adj update same PCI near card	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/01/02 11:37
L15	7	@ad<"20011220" and firmware adj update and PCI near card	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/01/02 11:38
L16	3	@ad<"20011220" and firmware adj update and PCI near card and wireless	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/01/02 11:38
S1	2	"6687496".pn.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/01/02 09:41
S2	2	"5819054".pn.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/07/05 12:57
S3	44	"43742" and JP	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/07/05 12:58

S4	16	"43742" and JP and japanese	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/07/05 13:00
S5	2	"4636942".pn.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/07/05 13:01
S6	2	"4636946".pn.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/07/05 13:02
S7	6	JP-B-61-43742	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/07/05 13:06
S8	3	61-43742	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/07/05 13:06
S9	0	@ad<"20011220" and wireless near fireware near update	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/12/31 13:49
S10	0	@ad<"20011220" and wireless near firmware near update	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/12/31 13:49
S11	16	@ad<"20011220" and wireless near firmware	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/12/31 14:01
S13	0	@ad<"20011220" and programmable near wireless near chip	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/12/31 14:02
S14	0	@ad<"20011220" and program$5 near wireless near chip	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/12/31 14:02

S15	561	@ad<"20011220" and program$5 same wireless same chip	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/12/31 14:02
S16	3	@ad<"20011220" and program$5 same wireless near chip	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/12/31 14:02
S17	1305	@ad<"20011220" and firmware near up$6	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/12/31 14:55
S18	272	S17 and wireless	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/12/31 14:03
S19	1	S18 and wireless near firmware	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/12/31 14:06
S20	17	("2003012091" "5,974,312" "6,414,871" "6,449.476" "6,603,394" "6,715,067" "6,229,737" "6,687,496").pn.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/12/31 14:08
S21	497	713/1,2,100.ccls. and wireless	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/12/31 14:08
S22	278	S21 and @ad<"20011220"	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/12/31 14:08
S23	12	S22 and automotive	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/12/31 14:11
S24	4	S22 and wireless.ti.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/12/31 14:09

S25	1	S22 and assembly adj line	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/12/31 14:11
S26	37	@ad<"20011220" and firmware near up$6 and car	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/12/31 14:56
S27	0	@ad<"20011220" and firmware near up$6 and car and assembly adj line	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/12/31 14:55
S28	0	@ad<"20011220" and firmware near up$6 near car	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/12/31 14:55
S29	31	@ad<"20011220" and firmware near up$6 and automobile	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/12/31 14:56
S31	0	S26 and firmware.ti.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/12/31 14:56
S32	0	vehicle adj firmware.ti.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/01/02 09:41
S33	0	vehicle near firmware.ti.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/01/02 09:42
S34	80	vehicle near firmware	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/01/02 09:43
S35	0	vehicle near firmware near update	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/01/02 09:42

S36	26	assembly adj line and electronic near program	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/01/02 09:44
S37	55	assembly adj line and electronic near program$5 and (car vehicle automo$5)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/01/02 09:44
S38	7	S37 and flash	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/01/02 09:45
S39	26	S37 and ROM	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/01/02 09:44
S40	32	S37 and @aD<"20011220"	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/01/02 10:10
S41	17	S40 and ROM	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/01/02 09:45
S42	12	@ad<"20011220" and integrated near BIOS and hard adj drive	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/01/02 10:10
S43	0	@ad<"20011220" and integrated near BIOS near hard adj drive	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/01/02 10:11
S44	1	@ad<"20011220" and integrated near BIOS near memory	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/01/02 10:14
S45	1	@ad<"20011220" and integrated same BIOS same flash adj disk	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/01/02 11:28

S46	0	@ad<"20011220" and PCB same BIOS same flash adj disk	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/01/02 10:14
S47	0	@ad<"20011220" and PCB same BIOS same flash adj drive	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/01/02 10:14
S48	4	@ad<"20011220" and BIOS same flash adj drive	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/01/02 10:24
S49	2	@ad<"20011220" and firmware same flash adj drive	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/01/02 10:25
S50	0	@ad<"20011220" and firmware same flash adj drive same board	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/01/02 10:25